

**Arm® Cortex®-M0**  
**32-bit Microcontroller**

# **NUC121/NUC125 Series CMSIS BSP**

## **Revision History**

*The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.*

*Nuvoton is providing this document only for reference purposes of NuMicro microcontroller and microprocessor based system design. Nuvoton assumes no responsibility for errors or omissions.*

*All data and specifications are subject to change without notice.*

For additional information or questions, please contact: Nuvoton Technology Corporation.

[www.nuvoton.com](http://www.nuvoton.com)

### Revision 3.01.007 (Released 2022-01-26)

---

- Standard driver
  - Improved infinite loop prevention with timeout counter and error code.
  - TIMER: TIMER\_Delay added return value.
- Sample code
  - I2C samples: Removed redundant code.
  - I2C and USCI\_I2C samples: Enabled schmitt trigger of I<sup>2</sup>C pins.
  - ISP\_I2C, ISP\_RS485, ISP\_UART: Added GCC project.
  - ISP\_MSC: Added.
  - USB\_D samples: Added software trim boundary.
  - USB\_D HID samples: Unified INT\_IN interval.
  - USB\_D\_MassStorage\_CDROM: Fixed Linux and Mac compatibility issue.

### Revision 3.01.006 (Released 2020-05-21)

---

- IAR startup\_NUC121.s: Fixed build issue with IAR V7.5.
- Standard driver
  - UART: UART\_DisableInt and UART\_EnableInt removed NVIC IRQ control.
- Sample code
  - I2C\_PDMA\_TRX: Removed unused \_\_ALIGNED.
  - PDMA, PDMA\_Scatter\_Gather: Added word alignment.
  - UART samples: Added NVIC IRQ control.
  - USB\_D\_MassStorage\_CDROM: Removed 2KB file size limit.
  - USB\_D\_VCOM samples: Fixed potential UART Tx FIFO overflow issue.
  - USB\_D\_VCOM\_DaulPort: Fixed wrong baudrate issue.
  - USCI\_SPI\_SlaveModeINT: Added.

### Revision 3.01.005 (Released 2020-09-14)

---

- Added Apache-2.0 license declaration.
- Standard driver
  - retarget.c
    - \_write and SendChar\_ToUART fixed '\r' issue.
    - SendChar fixed uninitialized pointer.
  - SPI: SPI\_DISABLE\_TX\_RX\_PDMA and SPI\_TRIGGER\_TX\_RX\_PDMA added.
  - TIMER: TIMER\_SET\_OPMODE added.
  - UART: UART\_PDMA\_DISABLE and UART\_PDMA\_ENABLE added.

- Sample code
  - I2C\_Wakeup\_Slave: Improved wakeup robustness.
  - UART samples, USCI\_UART\_TxRx\_Function: Fixed '\r' issue.
  - USB\_D\_VCOM\_DualPort: Fixed only one VCOM port in Linux.

#### Revision 3.01.004 (Released 2019-10-02)

---

- Standard driver
  - TIMER: TIMER\_Open fixed return value.
  - USCI\_SPI: USPI\_SET\_SS\_HIGH fixed implementation.
- Sample code
  - I2C\_PDMA\_TRX, ISP\_DFU, ISP\_I2C, ISP\_RS485, ISP\_SPI: Added.
  - FMC\_ExecInSRAM: Added IAR and GCC projects.
  - UART\_TxRx\_Function: Fixed data lost.

#### Revision 3.01.003 (Released 2019-06-19)

---

- Standard driver
  - I2C: Added error handling for new transfer.
  - TIMER: TIMER\_GetModuleClock used correct PCLK.
  - USB\_D: Fixed potential issue.
- Sample code
  - ISP samples: Added.
  - TIMER\_Delay: Used correct PCLK.
  - USB\_D samples: Fixed potential issue.
  - USB\_D\_Audio\_NAU8822, USB\_D\_Audio\_HID\_NAU8822: Cleared FIFO before play / record.

#### Revision 3.01.002 (Released 2018-12-28)

---

- CMSIS: Upgraded to v5.1.1.
- Standard driver
  - CLK: CLK\_PowerDown required HIRC / MIRC auto trim disabled.
  - PDMA: PDMA\_Open supported multiple open.
- Sample code
  - Keil projects used "NULink Debugger" instead of "Nuvoton Nu-Link Debugger".
  - Semihost fixed build failure with GCC toolchain 7-2018-q2.
  - I2S\_PDMA\_PlayRecord: Fixed race condition.
  - TIMER\_CaptureCounter: Fixed array access overflow.

- USB VCOM samples: Fixed UART baud rate calculation.
- USB VCOM And HID Transfer: Fixed buffer overflow.

### Revision 3.01.001 (Released 2018-06-27)

---

- NuMicro.h: Added.
- NUC121.h: Separated register declarations of each IP into distinct header files.
- Standard driver
  - USB: Fixed USB Control-In packet with the same size as endpoint limit.
- Sample code
  - Added Eclipse projects for GCC toolchain.
  - CLK\_ClockDetector, HIRC\_Trim, UART\_Wakeup\_LXT, ADC samples: Set analog pins as input mode and disabled digital input function.
  - PDMA\_ScatterGather\_PingPongBuffer: Added PDMA error handling.
  - UART\_PDMA: Added UART error handling.
  - USCI\_I2C\_Monitor: Added.

### Revision 3.00.003 (Released 2017-12-13)

---

- NUC121.h: TIMER\_CTL\_TRGDAC\_Pos and TIMER\_CTL\_TRGDAC\_Msk removed.
- Standard driver
  - I2C: I2C\_ReadByteTwoRegs, I2C\_ReadMultiBytesTwoRegs, I2C\_WriteByteTwoRegs, and I2C\_WriteMultiBytesTwoRegs fixed high byte lost.
  - SPI: I2S\_Open improved I2S sample rate accuracy.
  - TIMER: TIMER\_TRG\_TO\_EADC replaced with TIMER\_TRG\_TO\_ADC.
  - USB
    - USB\_L1RESUME replaced with USB\_STATE\_L1RESUME.
    - USB\_L1SUSPEND replaced with USB\_STATE\_L1SUSPEND.
  - USCI-I2C: UI2C\_ReadByteTwoRegs, UI2C\_ReadMultiBytesTwoRegs, UI2C\_WriteByteTwoRegs, and UI2C\_WriteMultiBytesTwoRegs fixed high byte lost.
  - USCI-UART: UART\_Open and UART\_SetLine\_Config fixed wrong baud rate.

### Revision 3.00.002 (Released 2017-03-09)

---

- NUC121.h: BPWM0\_IRQn and BPWM1\_IRQn added.
- Standard driver
  - BPWM: BPWM\_ConfigOutputChannel fixed 100% duty issue.

- CLK
  - CLK\_CLKSEL1\_ADCSEL\_HIRC\_DIV2 replaced with CLK\_CLKSEL1\_ADCSEL\_HIRC.
  - GPIOA\_MODULE, GPIOB\_MODULE, GPIOC\_MODULE, GPIOD\_MODULE, GPIOE\_MODULE, GPIOF\_MODULE fixed.
- I2C: I2C\_CLEAR\_WAKEUP\_WR\_STATUS removed.
- PWM: PWM\_ConfigOutputChannel fixed 100% duty issue.
- SYS
  - SYS\_GPF\_MFPL\_PF0MFP\_XT1\_OUT, SYS\_GPF\_MFPL\_PF0MFP\_X32\_OUT, SYS\_GPF\_MFPL\_PF1MFP\_XT1\_IN, and SYS\_GPF\_MFPL\_PF1MFP\_X32\_IN added.
  - SYS\_GPD\_MFPL\_PD3MFP\_UART0\_CTS replaced with SYS\_GPD\_MFPL\_PD3MFP\_UART0\_nCTS.
  - SYS\_GPD\_MFPL\_PD3MFP\_UART0\_RTS replaced with SYS\_GPD\_MFPL\_PD3MFP\_UART0\_nRTS.
- Sample code
  - BPWM\_DutySwitch: Fixed 100% duty issue.
  - FMC\_IAP: Fixed Wrong project setting.
  - LED\_Toggle, UART\_Wakeup\_LXT: Added.
  - PWM\_DutySwitch: Fixed 100% duty issue.
  - USB samples: Replied USB 2.1 version only if SUPPORT\_LPM defined.
  - USB\_Audio\_HID\_NAU8822: Fixed PD11 issue.
  - USCI\_UART\_TxRx\_Function: Fixed compilation error.

#### **Revision 3.00.001** (Released 2016-10-07)

---

- Primary release version.

### Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

---

*Please note that all data and specifications are subject to change without notice.  
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*